BRANZ Technical Opinion Group Number Assessment

This is to certify that the specimen described below has been tested by BRANZ Ltd on behalf of

Stoanz
72 Abel Smith Street
Te Aro
Wellington 6011
New Zealand

Test standards: ISO 5660 Parts 1 and 2, AS/NZS 3837:1998

Specimen name: StoSilent Direct

StoSilent Top BasicStoSilent FinishStoSilent Décor M

StoSilent Direct Colour Climasan

Specimen description: A mineral wool and expanded glass granulate interior lining

system with a paint-coated plaster finish.

Orientation: From the direction tested.

A full description of the test specimen and results are given in BRANZ Reports:

FH 6000-TT (test date 16 and 25 August 2016) and FH 6000-TO

Regulatory authorities are advised to examine test reports before approving any product.

The test results were the basis for the following:

Classification Document	Group Number Classification
NZBC Verification Method C/VM2 Appendix A	1-S
NCC Specification C1.10 Clause 4 determined in accordance with AS 5736.1	1

The average specific extinction area was less than the 250 m²/kg limit

Issue Date: Expiry Date:

ACCREDITED LABORATORY

20 October 2016 20 October 2021

All tests and procedures reported herein, unless indicated, have been performed in accordance with the laboratory's scope of accreditation.